



Attorney Docket No. 392.1849

Cert

UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Kentaro FUJIBAYASHI, et al.

Application No.: 10/735,705

ATTENTION

Confirmation No.: 3438

CERTIFICATE OF CORRECTION

Filed: December 16, 2003

BRANCH

U.S. Patent No.: 6,897,626 B2

Batch No.:

Issued: May 24, 2005

For: SYNCHRONOUS CONTROLLER

REQUEST FOR CERTIFICATE OF CORRECTION

**Certificate**  
JAN 31 2006  
**of Correction**

Commissioner for Patents  
PO Box 1450  
Alexandria, VA 22313-1450

Sir:


Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: 1-26-06

By:   
John C. Garvey  
Registration No. 28,607

1201 New York Ave, N.W., Suite 700  
Washington, D.C. 20005  
Telephone: (202) 434-1500  
Facsimile: (202) 434-1501

FEB 01 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.  
(Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE

## CERTIFICATE OF CORRECTION

PATENT NO : 6,897,626 *B2*

DATED : May 24, 2005

INVENTOR(S) : Kentaro FUJIBAYASHI, et al.

First Page, Column 2 (Foreign Patent Documents), line 2, change "083327" to --0 833 237--.

Column 2, line 64, change " $M=(X^2+Y^2)$ " to -- $M=(X^2+Y^2)^{1/2}$ --.

## MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP  
1201 New York Ave., N.W.  
Suite 700  
Washington, DC 20005

PATENT NO. 6,897,626

No. of add'l copies  
@ 50¢ per page

⇒

FEB 01 2006